Safety Alerts

1. **RECALL DATED 11th NOVEMBER 2026:** ONLY APPLICABLE TO A FEW BATCHES OF 8.4 mm LYNX DYNAMIC ROPE

If you have a NAMAH Lynx 8.4 mm or Genius 8.4 mm dynamic climbing rope, stop using it now. Do not use it for climbing, belaying, abseiling, rescue, work at height, or any other purpose where it could be called on to hold a fall.

The Hazard

Testing has shown that this rope can break after arresting only a small number of falls, and below the number required by the standard EN 892 for dynamic mountaineering ropes. We have confirmed non-compliance with the standard in our own testing.

A rope that breaks during a fall can cause serious injury or casualty.

The cause is under investigation. Until that investigation is complete, this rope must not be relied on to hold a fall.

How to identify the rope

Check the Batch number as:

NL-8.4-5413-260511-01,

NL-8.4-5413-260530-01,

NL-8.4-5413-260603-01,

NL-8.4-5413-260629-01,

NL-8.4-5413-260705-01,

Ma EUR nd band at each end of the rope. Supplied between May 2026 and July 2026. Lengths supplied: 5 units, Total Meters: 380 meters.

3. Contact us at info@namahropes.com to arrange a return.
4. Tell anyone who may have used or borrowed this rope, including climbing partners, clubs, gyms, schools, guiding operations and employers, that it must not be used. The full safety notice, which also covers refunds and contact details, is available here.

NOTE: ALL OTHER BATCHES OF THIS ROPE AND ALL OTHER ROPES PRODUCED BY NAMAH ARE NOT AFFECTED BY THIS RECALL.

NEWSLETTER

NEWSLETTER

Get 10% OFF when you subscribe to our newsletter. Sign up NOW!

Enter your email

© 2026 Namah International Private Limited. All Rights Reserved.
Namah Ropes is the brand operated by Namah International Private Limited.

Made with ❤ by **TechMac Digital**

English

EUR

English